

DAFTAR ISI

LEMBAR PENGESAHAN	Error! Bookmark not defined.
SURAT PERNYATAAN KARYA SENDIRI	Error! Bookmark not defined.
PERSEMBAHAN.....	Error! Bookmark not defined.
ABSTRAK.....	Error! Bookmark not defined.
ABSTRACT.....	Error! Bookmark not defined.
KATA PENGANTAR.....	Error! Bookmark not defined.
DAFTAR ISI	1
DAFTAR LAMPIRAN	Error! Bookmark not defined.
DAFTAR GAMBAR.....	Error! Bookmark not defined.
DAFTAR TABEL	Error! Bookmark not defined.
DAFTAR SINGKATAN DAN LAMBANG.....	Error! Bookmark not defined.
BAB I.....	Error! Bookmark not defined.
PENDAHULUAN.....	Error! Bookmark not defined.
1.1 Latar Belakang.....	Error! Bookmark not defined.
1.2 Rumusan Masalah.....	Error! Bookmark not defined.
1.3 Tujuan Penelitian	Error! Bookmark not defined.
1.4 Batasan Masalah	Error! Bookmark not defined.
1.5 Manfaat Penelitian	Error! Bookmark not defined.
1.6 Posisi Penelitian (<i>State of The Art</i>).....	Error! Bookmark not defined.
1.7 Kerangka Berpikir	Error! Bookmark not defined.
1.8 Sistematika Penulisan	Error! Bookmark not defined.
BAB II.....	Error! Bookmark not defined.
TINJAUAN TEORI	Error! Bookmark not defined.

2.1 Perkembangan Serat Optik	Error! Bookmark not defined.
2.2 Struktur Dasar Serat Optik	Error! Bookmark not defined.
2.2.1 <i>Singlemode Step Index</i>	Error! Bookmark not defined.
2.2.1 <i>Multimode</i>	Error! Bookmark not defined.
2.3 Parameter untuk kelayakan <i>power budget</i>	Error! Bookmark not defined.
2.4 Bit Error Rate (BER)	Error! Bookmark not defined.
2.5 Q-Factor	Error! Bookmark not defined.
2.6 Teknologi GPON (<i>Gigabit Passive Optical Network</i>)	Error! Bookmark not defined.
2.7 Komponen GPON	Error! Bookmark not defined.
2.7.1 <i>Network Management System (NMS)</i>	Error! Bookmark not defined.
2.7.2 <i>Optical Line Terminal (OLT)</i>	Error! Bookmark not defined.
2.7.3 <i>Optical Distribution Cabinet (ODC)/Rumah Kabel</i>	Error! Bookmark not defined.
2.7.4 <i>Optical Distribution Pack (ODP)</i>	Error! Bookmark not defined.
2.8 Kelebihan dan Kekurangan teknologi GPON ..	Error! Bookmark not defined.
2.9 Teknologi FTTx	Error! Bookmark not defined.
2.9.1 <i>Fiber To The Zone (FTTZ)</i>	Error! Bookmark not defined.
2.9.2 <i>Fiber To The Building (FTTB)</i>	Error! Bookmark not defined.
2.9.3 <i>Fiber To The Cube (FTTC)</i>	Error! Bookmark not defined.
2.9.4. <i>Fiber To The Home (FTTH)</i>	Error! Bookmark not defined.
BAB III	Error! Bookmark not defined.
METODOLOGI PENELITIAN	Error! Bookmark not defined.
3.1 Studi Literatur	Error! Bookmark not defined.
3.2 Pembuatan Konfigurasi Sistem Serat Optik	Error! Bookmark not defined.
3.3 Analisis <i>Power Budget</i>	Error! Bookmark not defined.
3.4 Survey	Error! Bookmark not defined.

3.5	Input Data Hasil Survey	Error! Bookmark not defined.
3.6	<i>Mapping Homepass</i> Menggunakan <i>Google Earth</i>	Error! Bookmark not defined.
3.7	<i>Drawing</i> Peta Lokasi & Skema menggunakan <i>Autocad</i>	Error! Bookmark not defined.
3.8	Analisis Proses.....	Error! Bookmark not defined.
3.9	Pengarsipan Dokumen	Error! Bookmark not defined.
BAB IV		Error! Bookmark not defined.
DESAIN FTTH PERUMAHAN BUMI PANYILEUKAN.....		Error! Bookmark not defined.
4.1	Kondisi <i>eksisting</i>	Error! Bookmark not defined.
4.2	Desain sistem FTTH bawah tanah untuk perumahan Bumi Panyileukan.....	Error! Bookmark not defined.
4.3	Hasil <i>mapping</i> menggunakan <i>Google Earth</i> ..	Error! Bookmark not defined.
4.4	<i>Mapping homepass</i> menggunakan <i>Google Earth</i>	Error! Bookmark not defined.
4.5	<i>Drawing</i> peta lokasi dan skema kabel menggunakan <i>autocad</i>	Error! Bookmark not defined.
BAB V		Error! Bookmark not defined.
ANALISIS TERHADAP DESAIN (FTTH) <i>FIBER TO THE HOME</i> BERDASARKAN HASIL MATRIKS MATERIAL DAN <i>POWER BUDGET</i>.....		Error! Bookmark not defined.
5.1	Analisis data hasil matriks material.....	Error! Bookmark not defined.
5.2	Analisis <i>power budget</i>	Error! Bookmark not defined.
5.2.1	Menghitung total redaman <i>downlink</i> dan <i>uplink</i> pada jarak terjauh.....	Error! Bookmark not defined.
5.1.2	Menghitung total redaman <i>downlink</i> dan <i>uplink</i> pada jarak terdekat.....	Error! Bookmark not defined.
5.3	Hasil simulasi dari <i>Optisystem</i>	Error! Bookmark not defined.
5.3.1	Konfigurasi <i>downlink</i> jarak kabel <i>feeder</i> terjauh	Error! Bookmark not defined.
5.3.2	Konfigurasi <i>uplink</i> jarak kabel <i>feeder</i> terjauh.....	Error! Bookmark not defined.

5.3.3 Konfigurasi <i>downlink</i> jarak kabel <i>feeder</i> terdekat	Error! Bookmark not defined.
5.3.4 Konfigurasi <i>uplink</i> terdekat.....	Error! Bookmark not defined.
5.4 Analisis hasil perancangan	Error! Bookmark not defined.
BAB VI	Error! Bookmark not defined.
KESIMPULAN DAN SARAN.....	Error! Bookmark not defined.
6.1 Kesimpulan.....	Error! Bookmark not defined.
6.2 Saran.....	Error! Bookmark not defined.
DAFTAR PUSTAKA	Error! Bookmark not defined.
LAMPIRAN	Error! Bookmark not defined.

